



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
October 19, 2010

Reviewed PRB

Mine Name: Dugway Pass	Permit Number: S/023/0091
Operator Name: Davies, Wingle & Davies, Inc.	Inspection Date: 10/13/2010
Inspector(s): Wayne Western	Time: 10:00 – 10:30 AM
Other Participants: Jerry Mansfield BLM	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 05/25/2014 **Bond Amount:** \$25,200

Purpose of Inspection: This was a routine annual inspection.

Inspection Summary: There is a trailer, a horse trailer and a sluice box and water tank on the site. No evidence of any recent mining activity. The BLM has concerns about the access road which is on BLM land. The road was put in as part of a BLM notice and the notice has since expired. The BLM many require reclamation of the road, that a special use permit be obtained or that another notice be filed. The Division is not directly involved with the BLM and the road. If the BLM does require that the road be reclaimed then the Division would have concerns about how the mine could be reclaimed.

Conclusions and Recommendations: Continue to monitor this site when in the area. The operator needs to maintain a cleaner site when not mining as well as saving topsoil from disturbed areas for reclamation.

Inspector's Signature

Wayne Western

WHW, BG:pb
cc: Roger Davies
Will Stokes – SITLA

Inspection Date: October 13, 2010
Page 2 of 2
S/023/0091

Jerry Mansfield@BLM.gov

O:\M023-Juab\S0230091-Dugwaypass\inspections\Insp-10132010.doc